

LAND CORNER RECORD

Index: V-15	Corner: 1/4 Corner between Sections 27 and 34	State of Indiana - Hoosier National Forest
Section: 27	Township: 7N Range: 1E P.M.: 2nd	County: Monroe
Coordinate:	Lat./N: 1369137.164 Long./E: 3147875.134	Datum: NAD83 IN West Zone, US Survey Feet


CORNER HISTORY: (Chronological history of corner)

1.) Date of Survey:	Surveyor:	Monument:	Recording Information:	Monument Photograph:
9/15/1982	Ken Anderson L.S. #80040545	A 3" stamped aluminum monument set	USDA Forest Service Bedford, IN	
Reference Objects:	Species:	Diameter:	Bearing:	Distance:
	Hickory	4"	N62°E	23.80'
	Cherry	15"	N36°E	25.70'
	Beech	18"	N48°W	10.40'
Record evidence of prior survey:				
2.) Date of Survey:	Surveyor:	Monument:	Recording Information:	
10/7/2008	Kevin Enright Monroe County Surveyor	A stamped 3" aluminum monument found	Monroe County Surveyor's Office Bk. 41, Pg. 46	
Reference Objects:	Species:	Diameter:	Bearing:	Distance:
	Shagbark Hickory	6"	N68°E	23.23'
	Kentucky Coffee	22"	N40°E	24.10'
	Metal Fence Post	N/A	S11°W	7.53'
Record evidence of prior survey:	A corner post with a "SURVEY" sign is N90°W - 0.40'			

ACCESSORIES: Bearing and distance from monument to witness object.

Reference Objects:	Object or Tree Species:	Diameter:	Bearing:	Distance:
** = no markings * = old blaze at base of tree and no paint	Shagbark Hickory*	6"	N68°E	23.67'
	Black Cherry*	31"	N43°E	25.36'
	Beech**	31"	N40°W	11.00'
	NE Barn Corner	N/A	S28°W	66.60'
Monument Found or Set:	A 3" aluminum monument stamped "T7N R1E 1/4 S.27 S.34 1982" found 0.4' above grade.			


MONUMENT SKETCH



NARRATIVE REFERENCE:

Monument is a 3" aluminum monument stamped "T7N R1E 1/4 S.27 S.34 1982" found 0.4' above grade, a carsonite post is located 1.5' east of the monument, located at the south end of a north-south running fence line, open yard to the west, +/- 300' north of St. Rd. 446, mature woods to the east, 6' northeast of a propane tank, 30' southeast of a pond, 100' east of a two story house, a 12" post is 0.1' west of the monument.

SECTION DIAGRAM



Corner Location = ●

PERPETUATION RECORD:

The record monument was found undisturbed and maintained by remarking two existing bearing trees establishing one new reference object. Three existing bearing trees were recovered from field notes by Ken Anderson, dated 9/15/1982. One existing bearing tree was recovered from a Monument Record by Kevin Enright, dated 10/7/2008.

Three bearing trees were marked with bearing tree sign, paint, and mag nail.

Referenced on BRCJ survey recorded as InstNo.2018007752

Accepted by the Monroe County Surveyor Review Board on August 6, 2019.

Section: 27 T7N R1E

Prepared By: BRCJ

(Project#3-0822)

Date: 5/2018

MONUMENT RECORD
State of Indiana - County of Monroe

Section: 34

Township: 7 North

Range: 1 East


Corner ID: Polk O-21

Monument Description & Remarks: 3" Aluminum Cap, " T7N R1E, 1/4 S.27/S.34, 1982".

Survey Sign 4ft above ground at pt. B

References On File: Lee Utt survey, Raymond Sipes (2004), on file in Recorder Office cabinet S, envelope 219/220

RECOVERY TIE DRAWING
Field Book 41 Page No. 46



- A - 3" Aluminum cap
- B - West 0.40' to Survey Sign on 15" corner post
- C - N 40° E 24.10' Sign on 22" Kentucky Coffee Tree
- D - N 68° E 23.23' to Sign on 6" Shagbark Hickory
- E - S 11° W 7.53' to 3" metal fence post

Not To Scale
Compass Bearing Magnetic North




I, Kevin P. Enright, Monroe County Surveyor, hereby certify that this document was prepared under my direction in accordance with the provisions of section 36-2-12-11 of the Indiana Code; and the above data is given under my hand and seal this 16th day of September, 2008.

Kevin P. Enright

Administered by the Monroe County Surveyor Review Board

Date: 10/7/2008



Index No. V-15
(Alphabetical-Numerical)


LAND CORNER RECORD
(RECTANGULAR SURVEYS)

R9-7150-4 (Rev. 6/13/67)
GPO 806-924

T. 7N R. 1E Mer. N.F. 2 County Monroe State Ind
Section 27 Corner common to sections 27 and 24

EXISTING SURVEYS

Original Government Survey		Original Evidence Found	
Year surveyed <u>1810</u>		Year of search <u>1972</u>	By <u>Robert L. Denton</u>
Original monument <u>Wood post</u> (Wood post, stone, pile of stones, pipe, etc.)		Monument found _____	
Bearing Trees		Original Bearing Trees Found	
Species <u>Dogwood</u>		Species _____	
Diameter <u>5"</u>		Diameter _____	
Bearing <u>S 89 W</u>	<u>N 72 E</u>	Bearing _____	
Distance <u>8 1/2</u>	<u>10 1/2</u>	Distance _____	
Subsequent Corner Restoration		Evidence of Subsequent Corner Restoration Found	
Year surveyed <u>1970</u>	By <u>Robert L. Denton</u>	Year of search <u>1972</u>	By <u>Robert L. Denton</u>
Where filed or recorded <u>Monroe County, Ind</u>			
Monument <u>Concrete post</u> (Original, concrete post, iron rod, etc.)			
Bearing Trees, Reference Objects		Bearing Trees, Reference Objects	
Species <u>Red Oak</u>	<u>Hickory</u>		
Diameter <u>3"</u>	<u>12"</u>		
Bearing <u>S 32 W</u>	<u>N 12 E</u>		
Distance <u>12 1/2</u>	<u>27 1/2</u>		



Sketch

○ Corner ■ F.S. Land

Relation of Evidence to Record Features Along Section Lines

Section line to sections _____
Object _____
Record distance _____
Measured distance _____

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any. Yes

Perpetuation Record

Monument and accessories established. Include brief description of area. _____

At time of search:

1. Did you have the record description?

Yes ✓ No _____

2. How was search area located?

Pacing, chaining, photos, maps, etc. photos, maps

3. Man hours spent in search 1/2

man hour

4. Do you think additional search might

recover evidence? Yes _____ No ✓

5. Signature R. Denton

Certified corner restoration certificate prepared: Yes _____ No _____

Filed in county records at _____ Date _____ County Document No. _____

Identified on aerial photo No. _____ Which is filed at _____